

PEMCO Inspection Company WLL

Vehicle Activity Report

Reporting Period :2025-08-21(12 AM -11.59PM)
Generated Date :2025-08-21 7.30 AM

Vehicle Name:192523-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	23:58:00	25.196081,51.386253	155	null
2	2025- 08-21	Overspeed	23:58:00	25.196081,51.386253	23:32:03	25.196081,51.386253	0	0

Vehicle Name:192423-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	23:24:22	25.196081,51.386253	155	null
2	2025- 08-21	Overspeed	23:24:22	25.196081,51.386253	22:07:35	25.196081,51.386253	0	0

Vehicle Name:152564-Hilux

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	20:50:31	25.196081,51.386253	155	null
2	2025- 08-21	hashbreak	20:50:31	25.196081,51.386253	18:10:03	25.196081,51.386253	0	0

Vehicle Name:192489-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	23:25:49	25.196081,51.386253	155	null
2	2025- 08-21	hashbreak	23:25:49	25.196081,51.386253	23:09:16	25.196081,51.386253	0	0

Vehicle Name:128926 **Driver Name:**

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	23:41:49	25.196081,51.386253	155	null
2	2025- 08-21	hashbreak	23:41:49	25.196081,51.386253	16:24:14	25.196081,51.386253	0	0

Vehicle Name:128725 **Driver Name:**

	SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	-	2025- 08-21	Overspeed	12:03:31	25.196081,51.386253	19:17:55	25.196081,51.386253	155	null
2	2	2025- 08-21	Overspeed	19:17:55	25.196081,51.386253	17:02:53	25.196081,51.386253	0	0