



PEMCO Inspection Company WLL

Vehicle Activity Report

Reporting Period :2025-09-03(12 AM -11.59PM)
Generated Date :2025-09-03 7.30 AM

Vehicle Name:192423-200 L

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|----------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 23:11:25 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | hashturn | 23:11:25 | 25.190588,51.423695 | 23:06:35 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:152564-Hilux

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|----------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 22:47:13 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | hashturn | 22:47:13 | 25.190588,51.423695 | 12:16:38 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:192489-200 L

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|-----------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 23:13:54 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | Overspeed | 23:13:54 | 25.190588,51.423695 | 22:54:41 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:128725

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------|--------|------------|----------------|----------|--------------|---------------|--------------|
|-------|------|--------|------------|----------------|----------|--------------|---------------|--------------|

| | | | | | | | | |
|---|------------|----------|----------|---------------------|----------|---------------------|-----|------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 19:43:34 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | hashturn | 19:43:34 | 25.190588,51.423695 | 19:16:17 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:128924

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|----------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 21:51:51 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | Seatbelt | 21:51:51 | 25.190588,51.423695 | 18:24:26 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:192523-200 L

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|------------------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 20:59:09 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | hashacceleration | 20:59:09 | 25.190588,51.423695 | 20:59:09 | 25.190588,51.423695 | 0 | 0 |

Vehicle Name:128926

Driver Name:

| SL NO | Date | Status | Start Time | Start Location | End time | End Location | Time Duration | Distance(KM) |
|-------|------------|----------|------------|---------------------|----------|---------------------|---------------|--------------|
| 1 | 2025-09-03 | Seatbelt | 14:14:18 | 25.190588,51.423695 | 23:11:13 | 25.190588,51.423695 | 453 | null |
| 2 | 2025-09-03 | Seatbelt | 23:11:13 | 25.190588,51.423695 | 20:47:01 | 25.190588,51.423695 | 0 | 0 |