



PEMCO Inspection Company WLL

Vehicle Activity Report

Reporting Period :2025-10-04(12 AM -11.59PM)
Generated Date :2025-10-04 7.30 AM

Vehicle Name:192523-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	19:07:52	25.188578,51.4456	12	null
2	2025-10-04	Overspeed	19:07:52	25.188578,51.4456	19:07:48	25.188578,51.4456	0	0

Vehicle Name:192423-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	17:25:59	25.188578,51.4456	12	null
2	2025-10-04	hashturn	17:25:59	25.188578,51.4456	16:16:24	25.188578,51.4456	0	0

Vehicle Name:128926

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	23:42:27	25.188578,51.4456	12	null
2	2025-10-04	hashturn	23:42:27	25.188578,51.4456	22:54:06	25.188578,51.4456	0	0

Vehicle Name:192489-200 L

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	23:47:24	25.188578,51.4456	12	null
2	2025-10-04	Overspeed	23:47:24	25.188578,51.4456	23:46:12	25.188578,51.4456	0	0

Vehicle Name:128924

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	19:10:07	25.188578,51.4456	12	null
2	2025-10-04	hashbreak	19:10:07	25.188578,51.4456	19:08:22	25.188578,51.4456	0	0

Vehicle Name:128725

Driver Name:

SL NO	Date	Status	Start Time	Start Location	End time	End Location	Time Duration	Distance(KM)
1	2025-10-04	Overspeed	12:01:34	25.188578,51.4456	23:02:20	25.188578,51.4456	12	null
2	2025-10-04	Seatbelt	23:02:20	25.188578,51.4456	21:44:11	25.188578,51.4456	0	0